

- CONDUCTED 16 MAY WITH FOLLOWING RESULTS:
- A. ALTERNATOR FAILED 18 MINUTES AFTER POWER APPLIED TO SYSTEMS.
- B. SYSTEM THREE PREFLIGHT AND POST FLIGHT GOOD. NO INTERCEPTS PRIOR POWER FAILURE.
- C. SYSTEM SIX PREFLIGHT AND POST FLIGHT GOOD.

FOLLOWI INTERCEPTS NOTED PRIOR POWER FAILURE:



IT IS QUITE EVIDENT PRESENT POWER SOURCE FOR THIS WILL BE SUBJECT SYSTEMS NOT OPERATIONAL RELIABLE. END OF MESSAGE SUBSEQUENT CABLES.

SECRET